

# Certificate

Rexroth Service Mobile / Rexroth Service Industrial

## Certified Service Center - Competence

We hereby confirm that the Hydraulic Service Center of

**Bosch Rexroth, spol. s. r. o.**  
**CZ-S1022**

located at

**Těžební 1238 / 2**  
**627 00 Brno**  
**Czech Republic**

has the infrastructure, qualified employees and processes in accordance with the guidelines of the Service Coordination Group to operate as a Certified Service Center. The scope of the audit includes the listed product areas and locations.

| Product Area                 | Location | Product Area Grading |
|------------------------------|----------|----------------------|
| Pumps and Motors             | Brno     | Competence           |
| Hydraulic Valves             | Brno     | Competence           |
| Large hydraulic Drives       | Brno     | Service Point        |
| Standard hydraulic Cylinders | Brno     | Standard             |
| Large hydraulic Cylinders    | Brno     | Service Point        |
| Mobile Gears                 | Brno     | Service Point        |
| Electronics                  | Brno     | Service Point        |

Based on audit report CZ-S1022All-RRH0307-CERT\_CSC-C\_CESU052019



on behalf of Service Coordination Group



on behalf of Service DC-MH

From DC-MH/SVM      Our Reference Mrs. Michaela Rützel      Telephone +497308822284      e-mail Michaela.ruetzel@boschrexroth.de

Lohr am Main, Elchingen  
05.08.19  
CZ-S1022All-RRH0307-  
CERT\_CSC-C\_CESU052019

**Memo**

Recipient Mr. R. Benes (DCEE/SVC)  
Cc Mr. M. Haase (DC-IH/SVC1), Mr. V. Tenhaeff (DC-IH/SVC12),  
Mr. G. Handke (DC-MH/SVM), Mr. J. Werner (DC-MH/SVM9)

**Service Audit**

Audit Date: 13.05.2019  
Audit Reference: CZ-S1022All-RRH0307-CERT\_CSC-C\_CESU052019

Re: Audit result

On behalf of the SCG (Service coordination group) Auditors, we thank you for your hospitality and cooperation during the recent Audit of your Service Center located at:

|                          |                |                |
|--------------------------|----------------|----------------|
| Service Center location: | Street name:   | Těžební        |
|                          | Street Number: | 2/1238,        |
|                          | City:          | 627 00 Brno    |
|                          | Country:       | Czech Republic |

The Service Centre was audited and we are pleased to announce the classification:

**Certified Service Center of Competence (CSC-C)**

The overall grading is based on the results of the listed product ranges:


| Product Range            | Grading       |
|--------------------------|---------------|
| Industrial Controls (CO) | Competence    |
| Axial Piston Units (AK)  | Competence    |
| Cylinders (CY)           | Standard      |
| Electronics (EL)         | Service Point |
| Mobile controls          | Competence    |
| Gear Units (GT)          | Service Point |

The results of the audit are summarised in the Audit Report, issued during the audit.  
ISO - Certification is required to achieve SC - level Advanced or Competence  
The grading is based on Document HSS 5710 01 02.  
The certificate is valid until: 2024


We congratulate you on your achievement

Sincerely

On behalf of the SCG:

  
Mr. Jürgen Werner  
DC-MH/SVM

Lead Auditor:

  
Mrs. Michaela Rützel  
DC-MH/SVM